Page 1

June-06-12 4:23:22 PM

Item ID: Revision ID:	D206-642-511			Accept	*N900040100*				Setup Sta	S1*		
Item Name:	Float Skidtub	e LH			A				Sto	p *N	*NS2*	
Start Date:	06/06/2012	Start Qty: 1.00	*	1*	Cust Item ID:							
Required Date:	15/06/2012	Req'd Qty: 1.00	*	1*	Custome	er:						
Reference: Approvals:	Process Pla	un: MLJ	Date: \\Z	/06/07 Tooling: SPC (Y/N):	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Date:		Ī	Run Sta	I/I	R1* R2*	
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours	Tool II	D Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	Rev	ision Nbr										
INN-D206-642	2 0											
100				0.00			-					
100 DC		DOCUMENT CONTRO Memo		0.00 QAS) aloslis					1151	1/30/5	
Document Control		Photocopy b	luefile and creat	e labels per PPP D206-642-5110	CHG004 J.B.							
110		Pick Kit		0.00						Į/ĺ	n	
110										الالحرا	(L) / (L) / (L)	

120

120

Quality Control

Packaging

Packaging

QC4-100% Inspect kits for completeness

0.0

0.00

Memo

Memo

0.00 (DAS) placis

(40)

Page 2

June-06-12 4:23:22 PM

Revision ID:	D206-642-51			Accept	*N900	040100)* Set	up Star	14.21
Start Date: Required Date: Reference:	06/06/2012 15/06/2012	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	D:			14(1)
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):		ate:	Rui	n Star Stop	"INK1"
Sequence ID/ Work Center ID 130 *130* Packaging Packaging)	Operation Description Packaging Memo Identify and Location:	pack for shipping as per	Set Up/ Run Hours 0.00 0.00 	Tool ID	Tool # Plan Code	-	Reject Qty	Reject Insp. Number Stamp
140 *140* QC Quality Control		QC21- Final Inspection • Memo	- Work Order Release	0.00			M	L5_	12/08/17 MF 12-08-17

June-06-12 4:23:26 PM

Work Order ID: 85362

85362

Parent Item:

D206-642-511

D206-642-511

Parent Item Name: Float Skidtube LH

Start Date: 06/06/2012

Required Date: 15/06/2012

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:B05.09.23Revised per D206-642 Rev. JKJ/JLM

As per IIN D206-642 Rev K IPP Rev:C 07-02-23

JLM

IPP rev D 07.06.06

EC

added K642-511 IPP Rev:E 07-12-05 ECN 1080p Rev L DD verified by:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D206-642-541 *D206-642 Replacement Skidtube		Manufactured	No	··		110	Each	0.0000	**	1 834	48	BS	58260
*K642-511 CHCCCX *K642-511 saddle kit 642-511	1*	Manufactured	No			110	Each	3.0000	**	1 8 <i>3</i> 93	- 7 JB		(2/08/03JB

Location Loc Qty Loc Code PKG 3

	•								DQA:	Date:			
NCR: Ye	es / N)			WORK ORDER NON	-CONFOR	MANCE / UPI	DATE					
									QA Closed:	Date:			
Work Orde	r:			ž.	DISPOSITION			AGAINST DE	PARTMENT	/PROCESS	€		
Part No					Rework Scrap Use-as-is Work Order Update	Ther	Skid-tube Crosstube Machining Small Fab Thermoforming Finishing Composite			d. Eng. Coor. re/Packaging Supplier Other	Engineering Quality		
NCR IV	U				work order opdate	_	Large rab	composite		Other			
Root				Descr	ription of work order update	Initial	Act	tion	Sign &				
Cause	Dat	Step	Qty		or Non-conformance	Chief Eng	Descr	ription	Date	Verification	QC Inspector		
Doc/Data	31												
quip/Tooling						,							
Operator		Ì		8									
Material													
Offset/Setup					4 10	13.5							
Other					. 1 7								
Process													
Supplier											,		
Training					•		1						
Unauthorized													
						FAULT CAT							
Landin	g Gear			_	Hardware	•	General		1		1		
·		ig Passes E			Breaking	Burrs			Maintenan	ce	Set-up		
<u> </u>	Centre Not Concentric to O/S			o/s	Missing		mination		Mislabeled		Supplier		
1	Cracks				Size/Length	\vdash	o Short		Off-Set		Temperature/Cure		
	Crushed/Crimp at Bending			ng	Spinning		Documentation/Data			Misread	Weld		
	Inspection Strip in Tube				Threading	 	Finish			ration	Wrong Stock Pulled		
	Other				Wrong		Inspection Incomplete			Out of Sequence			
ļ	Positioned Wrong				Drill Holes	—	Inspection Unqualified				Other		
, ,	Ripples on Inner Bend				Misaligned	\vdash	Instructions Incomplete/Unclear			Over/Under tolerance			
ļ ļ.	— 1	e Waves in		on _	Ovalized	—	Jigs/Fixtures/Tooling			Part Lost			
ļ.		g Sequenc		_	Over/Undersized	Kit Inc			Part Moved				
	Wave/Twist in Tube				Too Many	Kit Mis	Kit Missing			Raw Material			

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev F